




# Qualitative Infrared Survey of Building Heat Loss




**Location:** Front Entrance

**Notes:** Show air leakage at door.




**Location:** Front Entrance

**Notes:** Show air leakage at door.




**Location:** Master Bedroom, North Wall

**Notes:** Shows heat loss at top of wall (missing insulation) and AC line (cold spot indicated with white arrow) which can leak water (from condensation) inside wall.



**Location:** Master Bedroom, North Wall

**Notes:** Shows AC line (cold spot indicated with white arrow) which can leak water (from condensation) inside wall.



**Location:** Master Bedroom, North Wall, Inside and Outside

**Notes:** Shows AC line (cold spot indicated with white crosshair) which can leak water (from condensation) inside wall.




Inside view

Outside view




**Location:** Kitchen Rear Entrance

**Notes:** Shows door seal leaking.




**Location:** Kitchen Rear Entrance

**Notes:** Shows door sweep not properly sealing.




**Location:** Kitchen Rear Entrance

**Notes:** Shows door sweep not properly sealing.





**Location:** Kitchen Rear Entrance

**Notes:** Shows door sweep not properly sealing.





**Location:** 2<sup>nd</sup> Floor Kneewall Attic Door

**Notes:** Shows large air leak at top of door.




**Location:** 2<sup>nd</sup> Floor Kneewall Attic Door

**Notes:** Shows area of missing insulation beside door.




**Location:** 2<sup>nd</sup> Floor Kneewall Attic Door  
**Notes:** Shows large air leak at side of door.



**Location:** Attic Entrance

**Notes:** Shows attic door not properly insulated.



**Location:** 2<sup>nd</sup> Floor, Southwest Corner and Wall  
**Notes:** Shows large areas not properly insulated.

